

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  01D1026713	<b>(X3) Date Survey Completed</b>  12/16/2020
<b>Name of Provider or Supplier</b>  Alex City Internal Medicine	<b>Street Address, City, State</b>  3368 Highway 280 Suite 220, Alexander City, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5437</b>	<p><b>CALIBRATION AND CALIBRATION VERIFICATION</b> CFR(s): 493.1255(a)</p> <p>Unless otherwise specified in this subpart, for each applicable test system the laboratory must perform and document calibration procedures-- (1) Following the manufacturer's test system instructions, using calibration materials provided or specified, and with at least the frequency recommended by the manufacturer; (2) Using the criteria verified or established by the laboratory as specified in 493.1253(b) (3)-- (2)(i) Using calibration materials appropriate for the test system and, if possible, traceable to a reference method or reference material of known value; and (2)(ii) Including the number, type, and concentration of calibration materials, as well as acceptable limits for and the frequency of calibration; and (3) Whenever calibration verification fails to meet the laboratory's acceptable limits for calibration verification.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the Hematology calibration records, a review of the Beckman Coulter AcT Diff Operator's Manual, Testing Personnel (TP) #1's review of the patient test records, and an interview with TP #1, the laboratory failed to follow the manufacturer's instructions to perform quality controls after the calibrations, and before running patient samples. This was noted on two of five 2018-2020 calibrations reviewed. The findings include: 1. A review of Hematology records revealed the Beckman Coulter AcT Diff was calibrated on 09/04/2019 at 12:09 PM. However, quality control was not performed until 09/05/2019 at 8:23 AM. The instrument was also calibrated on 11/12/2020 at 11:44 PM without quality control being performed until 11/13/2020 at 8:13 AM . 2. A review of the Beckman Coulter AcT Diff Operator's Guide revealed in Chapter 5 Calibration (Page 5-18) "...17 Verify calibration by running 4C Plus cell control. See coulter 4C Plus Cell Control under Heading 2.2, Running Controls for instructions." 3. During an interview on 12/16 /2020 at 12:15 PM, Testing Personnel #1 confirmed the above noted findings, stating 6 patient CBC's (Complete Blood Counts) were performed on 09/04/2019 and 8</p>

patient CBC's performed on 11/12/2020 after the calibrations were run and before the quality controls were performed the following day.