

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D2031737	<b>(X3) Date Survey Completed</b>  03/03/2020
<b>Name of Provider or Supplier</b>  Biochemical And Molecular Genetics	<b>Street Address, City, State</b>  1501 Nw 10th Ave Brb Rm 531, Miami, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A recertification survey conducted on 03/03/2020 found that Biochemical and Molecular Genetics Clinical Laboratory was not in compliance with 42 CFR Part 493, Requirements for Laboratories.
<b>D3011</b>	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on the Occupational Safety and Health Administration (OSHA) regulations for Nitrogen storage, and based on observation and interview with laboratory staff, the laboratory failed to have an Oxygen sensor in the Liquid Nitrogen Storage Area. Findings include: Review of the OSHA procedure for Nitrogen storage, revealed that it is a requirement that for any indoor Nitrogen storage to have an Oxygen level sensor. Observation of the laboratory revealed that: The laboratory has 2 large Nitrogen Tanks in a closed laboratory area. No sensor for Oxygen level detection was available. During an interview on 03/03/2020 at 9:30 AM, the laboratory director confirmed that there was no Oxygen sensor available to monitor acceptable levels.</p>