

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 01D2017133	(X3) Date Survey Completed 07/23/2025
Name of Provider or Supplier Valley Pain Clinic	Street Address, City, State 2208 Danville Rd St G, Decatur, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5481	<p>CONTROL PROCEDURES CFR(s): 493.1256(f)(g)</p> <p>(f) Results of control materials must meet the laboratorys and, as applicable, the manufacturers test system criteria for acceptability before reporting patient test results. (g) The laboratory must document all control procedures performed.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the Thermoscientific Indiko Plus Toxicology analyzer quality control (QC) records, the patient results log, policies and procedures, and an interview with the Technical Consultant, the laboratory failed to ensure at least two levels of QC were run and acceptable prior to analyzing patient specimens and reporting the results. This was noted for 5 days out of 2 months reviewed in 2024. The findings include: 1. A review of the QC records for the Thermoscientific Indiko Plus Toxicology analyzer revealed the following dates QC was out prior to patient testing: a) 2/20/2024: Buprenorphine (BUP) Hi and Lo out; 14 patients affected. b) 2/21/2024: BUP Hi and Lo out; 16 patients affected. c) 2/22/2024: BUP Hi and Lo out; 19 patients affected. d) 6/24/2024: 6-Acetylmorphine (6AM) Hi and Lo out; 12 patients affected. e) 6/25/2024: No documentation of QC; 22 patients affected. 2. A review of the policies and procedures revealed, " Indiko Plus Daily Quality Control Procedure Actions to Take: 2. If any test has both QCs out, recalibrate and rerun." There was no evidence of corrective action documentation. 3. During an interview on 7/23/2025 at 12:09 PM, the Technical Consultant confirmed the above findings.</p>