

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  03D2248662	<b>(X3) Date Survey Completed</b>  08/21/2024
<b>Name of Provider or Supplier</b>  Tri-City Cardiology Consultants Pc	<b>Street Address, City, State</b>  143 S 63rd St, Mesa, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6046</b>	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a record review of competency assessments from 2024, and interview with the technical consultant (TC-2), the technical consultant failed to evaluate the competency of one of one testing personnel. Findings include: 1. The laboratory failed to provide evidence that indicated a qualified technical consultant performed and evaluated the 2024 annual competency for one of one testing personnel. 2. The TP-2 interviewed on 8/21/24 at 2:00 PM confirmed the technical consultant failed to evaluate the competency of one of one testing personnel in 2024.</p>