

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  11D2160839	<b>(X3) Date Survey Completed</b>  10/26/2021
<b>Name of Provider or Supplier</b>  Primary Pediatrics, Bonaire	<b>Street Address, City, State</b>  104 Bluff Chase, Suite A, Bonaire, GA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A Clinical Laboratory Improvement Amendments (CLIA) Recertification survey was completed on October 25, 2021. The laboratory was not in compliance with applicable CLIA requirements found at 42 CFR 493.1 through 42 CFR 493.1780. The following deficiencies were cited:
<b>D5439</b>	<p><b>CALIBRATION AND CALIBRATION VERIFICATION</b> CFR(s): 493.1255(b)</p> <p>Unless otherwise specified in this subpart, for each applicable test system the laboratory must do the following: Perform and document calibration verification procedure - (b)(1) Following the manufacturer's calibration verification instructions; (b)(2) Using the criteria verified or established by the laboratory under 493.1253(b)(3) -- (b)(2)(i) Including the number, type, and concentration of the materials, as well as acceptable limits for calibration verification; and (b)(2)(ii) Including at least a minimal (or zero) value, a mid-point value, and a maximum value near the upper limit of the range to verify the laboratory's reportable range of test results for the test system; and (b)(3) At least once every 6 months and whenever any of the following occur: (b)(3)(i) A complete change of reagents for a procedure is introduced, unless the laboratory can demonstrate that changing reagent lot numbers does not affect the range used to report patient test results, and control values are not adversely affected by reagent lot number changes. (b)(3)(ii) There is major preventive maintenance or replacement of critical parts that may influence test performance. (b)(3)(iii) Control materials reflect an unusual trend or shift, or are outside of the laboratory's acceptable limits, and other means of assessing and correcting unacceptable control values fail to identify and correct the problem. (b)(3)(iv) The laboratory's established schedule for verifying the reportable range for patient test results requires more frequent calibration verification.</p> <p>This STANDARD is not met as evidenced by: Based on review of the calibration documents for the Cell Dyn Emerald (Emerald),</p>

and staff interview, the laboratory failed to perform calibration every six months. Findings: 1. Review of the calibration documents, the laboratory performed calibration on the Emerald the following dates: 09/2021 03/2021 02/2020 (13 months) 2. Interview with staff #2 (CMS 209), and the Lab Manager, on October 26, 2021 at approximately 12:30 pm in the breakroom, confirmed the aforementioned documentation.

**D6004**

**LABORATORY DIRECTOR RESPONSIBILITIES**

CFR(s): 493.1407(a)(b)

The laboratory director is responsible for the overall operation and administration of the laboratory, including the employment of personnel who are competent to perform test procedures, and record and report test results promptly, accurate, and proficiently and for assuring compliance with the applicable regulations. (a) The laboratory director, if qualified, may perform the duties of the technical consultant, clinical consultant, and testing personnel, or delegate these responsibilities to personnel meeting the qualifications of 493.1409, 493.1415, and 493.1421, respectively. (b) If the laboratory director reappoints performance of his or her responsibilities, he or she remains responsible for ensuring that all duties are properly performed.

This STANDARD is not met as evidenced by:

Based on review of the calibration documents for the Cell Dyn Emerald (Emerald), and staff interview, the Laboratory Director (LD) failed to verify the calibration for the Emerald was performed every six months. Findings: 1. Review of the calibration documents, the laboratory performed calibration on the Emerald the following dates: 09/2021 03/2021 02/2020 (13 months) 2. Interview with staff #2 (CMS 209), and the Lab Manager, on October 26, 2021 at approximately 12:30 pm in the breakroom, confirmed the aforementioned documentation.