

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 19D2113375	(X3) Date Survey Completed 12/29/2021
Name of Provider or Supplier Lindsay York, Md, Llc	Street Address, City, State 1111 Medical Center Blvd N803, Marrero, LA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6040	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(2)</p> <p>The technical consultant is responsible for-- (b)(2) Verification of the test procedures performed and the establishment of the laboratory's test performance characteristics, including the precision and accuracy of each test and test system.</p> <p>This STANDARD is not met as evidenced by: A Follow-up survey was performed at Lindsay York, MD, LLC-CLIA# 19D2113375 on December 29, 2021. Based on review of the laboratory's Plan of Correction, record review, and interview with personnel, the Technical Consultant failed to ensure performance specification verification studies were complete. Refer to D5421.</p>
D6042	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(4)</p> <p>(b) The technical consultant is responsible for-- (b)(4) Establishing a quality control program appropriate for the testing performed and establishing the parameters for acceptable levels of analytic performance and ensuring that these levels are maintained throughout the entire testing process from the initial receipt of the specimen, through sample analysis and reporting of test results;</p> <p>This STANDARD is not met as evidenced by: A Follow-up survey was performed at Lindsay York, MD, LLC-CLIA# 19D2113375 on December 29, 2021. Based on review of the laboratory's Plan of Correction, record review, and interview with personnel, the Technical Consultant failed to ensure the quality control program was established to assure the quality of laboratory testing. Refer to D5469..</p>