

| | | |
|--|---|---|
| Statement of Deficiencies | (X1) Provider/Supplier/CLIA Identification Number 21D1032562 | (X3) Date Survey Completed 11/24/2025 |
| Name of Provider or Supplier Skin Care Specialty Physicians Llc | Street Address, City, State 1447 York Road Suite 301, Lutherville, MD | |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. | | |

| (X4) ID Prefix Tag | Summary Statement of Deficiencies |
|---------------------------|--|
| D5601 | <p>HISTOPATHOLOGY CFR(s): 493.1273(a)(f)</p> <p>(a) As specified in 493.1256(e)(3), fluorescent and immunohistochemical stains must be checked for positive and negative reactivity each time of use. For all other differential or special stains, a control slide of known reactivity must be stained with each patient slide or group of patient slides. Reactions of the control slide with each special stain must be documented.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview the histology laboratory (MOHS surgery) did not have a written quality control procedure to perform and document that the reactivity of the immunohistochemistry stains reacted as expected prior to reporting patient results. 1. The laboratory performs MART-1, SOX-10, CK-5 and CK-7 stains on patient tissue during MOHS surgery. 2. The written procedure for each immunohistochemistry stain did not have written procedures describing how the laboratory ensures that each stain is working by checking reactivity with a tissue testing positive for each stain and how this quality control check is documented in the testing records. 3. As an example, the histotechnician stated, during interview on November 24, 2025 at 11:00 am, that the surgeon would sometimes include a piece of patient skin tissue as a positive check for the Mart-1 stain, but the surgeon did not always do this.</p> |