

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D1091053	(X3) Date Survey Completed 05/02/2023
Name of Provider or Supplier Feinstein Laboratory	Street Address, City, State 29829 Telegraph Road Ste 203, Southfield, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3011	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: . Based on observation, record review, and interview with the Laboratory Director, the laboratory failed to ensure testing personnel followed established safety procedures while handling blood specimens for 1 (Testing Personnel #2) of 2 testing personnel observed. Findings include: 1. The surveyor observed Testing Personnel #2 (TP2) perform Complete Blood Count testing on 5/2/23 at 9:12 am. TP2 had one glove on their left hand and mixed the sample with the gloved hand before sampling. TP2 took the glove off and continued to handle the specimen without gloves after the specimen had been sampled. 2. A review of the laboratory's "Universal Precautions" policy revealed a section stating, "All laboratory personnel will wear protective devices to prevent skin and mucous membranes from coming in contact with patient blood and other body fluids. Gloves will be worn when obtaining and handling patient specimens." 3. An interview on 5/2/23 at 9:15 am with the Laboratory Director confirmed TP2 had not observed the laboratory's established safety procedures while handling blood specimens.</p>