

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 25D2078026	(X3) Date Survey Completed 03/06/2024
Name of Provider or Supplier Csl Plasma, Inc	Street Address, City, State 9245 Highway 49, Gulfport, MS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5209	<p>PERSONNEL COMPETENCY ASSESSMENT POLICIES CFR(s): 493.1235</p> <p>As specified in the personnel requirements in subpart M, the laboratory must establish and follow written policies and procedures to assess employee and, if applicable, consultant competency.</p> <p>This STANDARD is not met as evidenced by: Based on review of the laboratory's Technical Consultant Annual Recertification policy, the CMS 209 personnel form, and personnel records, the laboratory failed to establish a written policy and procedure to assess technical consultant competency for technical consultant responsibilities at this laboratory. Findings include: 1. The laboratory's Technical Consultant Annual Recertification policy states that technical consultant competency assessment is to be performed. The policy does not include the identification of the individual, listed on the CMS 209 personnel form, responsible for assessing the competency of the technical consultant. 2. Review of the CMS 209 personnel form and personnel records since the last survey on 8/24/2022 revealed that two of two annual competency assessments of the technical consultant, for both 2022 and 2023, were performed by an individual other than the laboratory director listed on the CMS 209 personnel form.</p>