

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  31D2000860	<b>(X3) Date Survey Completed</b>  09/21/2021
<b>Name of Provider or Supplier</b>  Premier Brain And Spine Llc	<b>Street Address, City, State</b>  2500 Morris Avenue, Union, NJ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6086</b>	<p><b>LABORATORY DIRECTOR RESPONSIBILITIES</b> CFR(s): 493.1445(e)(3)(ii)</p> <p>The laboratory director must ensure that verification procedures used are adequate to determine the accuracy, precision, and other pertinent performance characteristics of the method.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the Performance Specification (PS) records and interview with the Technical Supervisor (TS), the Laboratory Director failed to ensure that PS were adequate to perform Urine Toxicology tests on the Applied Biosystem Sciex Triple Quad 4500 system from 9/1/21 to the date of survey. The finding include: 1. Sample stability studies were not performed. 2. The TS confirmed on 9/21 /21 at 2:20 pm that the LD did not ensure the PS were adequate.</p>