

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 38D2047226	(X3) Date Survey Completed 05/27/2022
Name of Provider or Supplier Urgent Care Express DbA Portland Urgent Care	Street Address, City, State 4160 Ne Sandy Blvd, Portland, OR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Review of Personnel records and discussion with the staff the laboratory's Technical Consultant (TC) failed to perform competency assessment of two testing personnel (TP) for the year 2021 and 2022. Findings include: 1. Two out of seven testing personnel performing moderate complexity testing do not have documentation of their competency assessment. 2. One testing personnel hired 11/2020 do not have documentation of 6 months and yearly competency assessment. 3. One testing personnel hired 04/2021 do not have documentation of 6 months competency and yearly competency assessment. 4. Discussion with the staff confirmed these findings on 05/27/2022 @ 15:00PM.</p>