

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b> 44D2027100	<b>(X3) Date Survey Completed</b> 07/10/2019
<b>Name of Provider or Supplier</b> Dyersburg Family Walk In Clinic	<b>Street Address, City, State</b> 1516 East Reelfoot Ave, Union City, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D2010</b>	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(2)</p> <p>The laboratory must test samples the same number of times that it routinely tests patient samples.</p> <p>This STANDARD is not met as evidenced by: Based on review of the 2018 and 2019 complete blood count proficiency testing (PT) records and interview with testing personnel number one, the laboratory failed to perform the PT samples in the same manner as patient testing. The findings include: 1) Review of the 2018 and 2019 PT records revealed in the 2018 events two, three, 2019 event one, the PT samples were performed twice in the same day. 2) Interview on July 10, 2019 at 11:00 a.m. with testing personnel number one confirmed the PT samples are performed twice and patient samples are performed once.</p>