

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 49D0016288	(X3) Date Survey Completed 02/07/2018
Name of Provider or Supplier Vpi And Student Health Services Laboratory	Street Address, City, State Mccomas Hall, Virginia Tech, 895 Washington St, Sw, Blacksburg, VA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at VPI and Student Health Center- Schiffert Health Center on February 7, 2018 by the Virginia Department of Health's Office of Licensure and Certification. The laboratory was surveyed under 42 CFR part 493 CLIA Requirements. Specific deficiencies cited are as follows:
D6120	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the Laboratory Personnel Report form (CMS 209), testing personnel (TP) files, and an interview, the technical supervisor (TS) failed to assess annual competency for one (1) of four (4) testing personnel for 2016 and 2017. Findings include: 1. Review of the CMS Form 209: Laboratory Personnel Report revealed that the laboratory director serves as the TS, and that there are four (4) testing personnel in the laboratory. 2. Review of TP files revealed no competency assessments in 2016 and 2017 for: Testing personnel A. (See Personnel Code Sheet.) 3. An interview with the general supervisor at approximately 2:45 PM on February 7, 2018 confirmed that the technical supervisor failed to assess competency for the TP listed above.</p>