

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 53D2055106	(X3) Date Survey Completed 09/28/2026
Name of Provider or Supplier Cedars Health	Street Address, City, State 428 South Durbin Suite 104, Casper, WY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A validation survey was conducted by the Wyoming CLIA state agency at Cedars Health located at 428 South Durbin Street, Suite 104, in Casper, WY on 9/28/26.
D5437	CALIBRATION AND CALIBRATION VERIFICATION CFR(s): 493.1255(a) (a)Unless otherwise specified in this subpart, for each applicable test system the laboratory must perform and document calibration procedures-- (a)(1) Following the manufacturer's test system instructions, using calibration materials provided or specified, and with at least the frequency recommended by the manufacturer; (a)(2) Using the criteria verified or established by the laboratory as specified in 493.1253(b)(3)-- (a)(2)(i) Using calibration materials appropriate for the test system and, if possible, traceable to a reference method or reference material of known value; and (a)(2)(ii) Including the number, type, and concentration of calibration materials, as well as acceptable limits for and the frequency of calibration; and (a)(3) Whenever calibration verification fails to meet the laboratory's acceptable limits for calibration verification. This STANDARD is not met as evidenced by: Based on lack of documentation, review of the manufacturer's operator's manual, and staff interview, the laboratory failed to follow the Sysmex XP-300 manufacturer's instructions to perform an instrument calibration once every 6 months for 4 out of 4 years reviewed (2023, 2024, 2025, 2026). The laboratory performed approximately 1,600 complete blood count patient tests per year. The findings were: 1. Review of the laboratory's hematology records showed the last certificate of calibration was dated 1 /26/23. 2. Review of the Sysmex XP-300 operator's manual showed calibration frequency was a minimum of every 6 months or after major maintenance or part replacement. 3. Interview with the laboratory director on 9/28/26 at 4:30 PM confirmed there was no documentation to show the Sysmex XP-300 had been calibrated since 1/26/23.