Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	10D0683000	10/15/2020
Name of Provider or Supplier	**Street Address, City, State**	
Urology Group Of Florida Llc	4889 S Congress Ave, Lake Worth, FL	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced recertification survey was conducted at Urology Group of Florida on 10 /15/20. The laboratory is not in compliance with Code of Federal Regulations (CFR), Part 493, requirements for clinical laboratories.
D6128	TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9) The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least annually after the first year, unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individual's performance must be reevaluated to include the use of the new test methodology or instrumentation. This STANDARD is not met as evidenced by: Based on record review and interview with laboratory personnel, there was no documentation to indicate that the technical supervisor evaluated the performance of the one non-physician high complexity testing person over the past two years. The findings included: Review of personnel competency records for the past two years on 10/15/20 revealed that there were no documented competency evaluations for the medical technologist. During an interview with this testing person at 10:05 a.m. on 10 /15/20, she said that there were no evaluations of her over the past two years.