Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1038689	(X3) Date Survey Completed 12/11/2024
Name of Provider or Supplier J Brahmatewari Md Pa	**Street Address, City, State** 4445 W 16th Ave Ste 402, Hialeah, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A recertification survey was conducted from December 06, 2024 to December 11, 2024. J BRAHMATEWARI MD PA clinical laboratory was not in compliance with 42 CFR 493, requirements for clinical laboratories.
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on observation, record review, and staff interview the laboratory failed to store 100% Reagent alcohol, Eosin-Y Alcoholic 0.25% and X-S Xylene Substitute according to the "STATLAB" manufacturer's instructions at least since 02/06/2023. The findings included: 1-During a tour of the laboratory on 12/06/2024 at 02:45 PM., observed 1 full gallon and 1/3 gallon of 100% Reagent alcohol, 2/3 gallon of Eosin-Y Alcoholic 0.25%, and one full gallon of X-S Xylene Substitute under a bench cabinet with a sign "CHEMICAL STORAGE". 2-Review of STATLAB product label placed in front of the reagent Eosin-Y Alcoholic 0.25% and X-S Xylene Substitute, stated in the storage section "Keep container tightly closed in a fireproof locked place." 3-Review of the safety data sheet for 100% Reagent alcohol revealed that the storage conditions were to "Store locked up." 4-Interview on 12/06/2024 at 03:11 PM the laboratory's risk assessment consultant confirmed that the reagents were not stored locked or in a flammable cabinet.