Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1091593	(X3) Date Survey Completed 03/05/2024
Name of Provider or Supplier Coastal Skin Surgery And Dermatology	**Street Address, City, State** 12469 Emerald Coast Pkwy Ste 101, Miramar Beach, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An on - site announced CLIA recertification survey was conducted at Coastal Skin Surgery on 03/05/24. The laboratory is not in compliance with 42 CFR Part 493, Requirements for Laboratories. The following is a description of the standard level deficiencies:
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on interview with the Mohs Technician, observation of the Laboratory Director's office closet, and review of the Avantik UltraClear Xylene Substitute (Xylene Substitute) Safety Data Sheet (SDS) , the laboratory failed to follow manufacturer's instructions for Xylene Substitute disposal and storage. Findings Included: -Interview with the Mohs Technician on 03/05/24 at 9:03 a.m., revealed the Xylene Substitute was discarded down the drain after use. - Observation of the Laboratory Director's closet on 03/05/24 at 9:10 a.m., revealed seven bottles of Xylene Substitute that were not contained in a fireproof cabinet. -Review of the Avantik Xylene Substitute SDS revealed that Xylene Substitute must be stored in a fireproof location and kept out of sewers and waterways, because it is a hazard to the aquatic environment.