

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 01D2312279	(X3) Date Survey Completed 09/09/2026
Name of Provider or Supplier Dba Alabama Oncology	Street Address, City, State 3686 Grandview Parkway--Plaza I, Suite 540, Birmingham, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5437	CALIBRATION AND CALIBRATION VERIFICATION CFR(s): 493.1255(a) (a)Unless otherwise specified in this subpart, for each applicable test system the laboratory must perform and document calibration procedures-- (a)(1) Following the manufacturer's test system instructions, using calibration materials provided or specified, and with at least the frequency recommended by the manufacturer; (a)(2) Using the criteria verified or established by the laboratory as specified in 493.1253(b) (3)-- (a)(2)(i) Using calibration materials appropriate for the test system and, if possible, traceable to a reference method or reference material of known value; and (a) (2)(ii) Including the number, type, and concentration of calibration materials, as well as acceptable limits for and the frequency of calibration; and (a)(3) Whenever calibration verification fails to meet the laboratory's acceptable limits for calibration verification. This STANDARD is not met as evidenced by: Based on a review of the Hematology calibration records, and an interview with the Technical Consultant (TC), the laboratory failed to perform calibrations on the Emerald Cell-Dyn Hematology analyzer every six months. This was noted for one of two calibrations due in 2026. The findings include: 1. A review of the Hematology calibration records revealed the Emerald Cell-Dyn was last calibrated on 10/10/25. There was no calibration documented for the first half of 2026. 2. The TC confirmed the findings during the exit interview on 9/9/26 at 1:45pm.