

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 02D1036810	(X3) Date Survey Completed 07/31/2026
Name of Provider or Supplier Nick Sarrimanolis Md Llc	Street Address, City, State 1867 Airport Way Suite 145b, Fairbanks, AK	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5481	CONTROL PROCEDURES CFR(s): 493.1256(f)(g) (f) Results of control materials must meet the laboratorys and, as applicable, the manufacturers test system criteria for acceptability before reporting patient test results. (g) The laboratory must document all control procedures performed. This STANDARD is not met as evidenced by: Based on a review of Chemistry Quality Control (QC) records and an interview with Testing Person (TP1), the laboratory failed to ensure the quality control results were within the manufacturer's acceptable ranges prior to reporting patient Calcium results, and the laboratory failed to document corrective actions taken when the control results were not within the manufacturer's acceptable ranges for 16 of 18 days in February 2026. Findings include: 1. A review of QC records for the Siemens Dimension EXL 200 for the month of February 2026 revealed: a. Biorad Liquid Assayed Multiquel Level 1 QC Lot #46021 Calcium results were outside the manufacturer's acceptable range for 16 of 18 days reviewed, and no corrective actions were documented. b. Biorad Liquid Assayed Multiquel Level 3 QC Lot #46023 Calcium results were outside the manufacturer's acceptable range for 8 of 18 days reviewed, and no corrective actions were documented. 2. An on-site interview with TP1 on 7/31/26 at 11:30 AM confirmed that the QC results were outside the manufacturer's range and no corrective actions were documented. 3. The lab reported performing 78 Calcium tests in February 2026, and 29,320 chemistry tests annually.