

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 09D2322604	(X3) Date Survey Completed 09/04/2026
Name of Provider or Supplier Foxhall Dermatology	Street Address, City, State 4910 Massachusetts Ave Suite 308, Washington, DC	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced on-site initial survey was performed on 09/04/26. Standard-level deficiencies cited.
D5401	PROCEDURE MANUAL CFR(s): 493.1251(a) (a) A written procedures manual for all tests, assays, and examinations performed by the laboratory must be available to, and followed by, laboratory personnel. Textbooks may supplement but not replace the laboratory's written procedures for testing or examining specimens. This STANDARD is not met as evidenced by: Based on the laboratory's written procedures, patient reports, and interview with the Mohs manager, the laboratory failed to follow its own written procedure for 1 of 8 patient slides. Findings included: 1. On 09/04/26 at 09:30 am, the Mohs manager confirmed the laboratory performed frozen tissue sectioning using the Leica CM 1850 Cryostat. 2. A review of the laboratory's written procedure titled, "LABELING SLIDES" stated, "In this facility, ALL SLIDES for frozen section specimens will be labeled as follows: 1. Date 2. Name of patient 3. Mohs # 4. Stage # 5. Number of specimen block". 3. A review of patient reports revealed the incorrect visit date on the slides for 1 of 8 patients reviewed. a. Patient 4379125 visit date on the report 04/03/26 - Slide I-1A documented visit date 04/02/26, Slide I-1B documented visit date 04/02/26 and Slide II-1A documented visit date 04/02/26. 4. Interview on 09/04/26 at 10:00 am with the Mohs manager confirmed the findings above. 5. A review of the laboratory's test volumes revealed an annual test volume of approximately 150 frozen tissue sections annually.
D5429	MAINTENANCE AND FUNCTION CHECKS CFR(s): 493.1254(a)(1)

(a)(1) Maintenance as defined by the manufacturer and with at least the frequency specified by the manufacturer.

This STANDARD is not met as evidenced by:

Based on manufacturer's instructions, review of maintenance records, and interview with the Mohs manager, the laboratory failed to perform a maintenance procedure as required by the manufacturer for 4 of 4 weeks. Findings included: 1. On 09/04/26 at 09:30 am, the Mohs manager confirmed the laboratory performed frozen tissue sectioning using the Leica CM 1850 Cryostat. 2. A review of the Leica CM 1850 Cryostat operator's manual (page 41) section "9.3.1 General maintenance" stated, "Once a week: Apply a drop of oil to the plastic coupling". 3. A random review of the laboratory's maintenance log from 04/01/26 through 04/30/26 revealed no evidence the laboratory followed the manufacturer's weekly maintenance instructions for 4 of 4 weeks. 4. An interview on 09/04/26 at 10:10 am with the Mohs manager confirmed the findings above. 5. A review of the laboratory's test volumes revealed an annual test volume of approximately 150 frozen tissue sections annually.