

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D0701312	(X3) Date Survey Completed 08/06/2026
Name of Provider or Supplier Nancy S Ling Md Pa	Street Address, City, State 305 Bryan Rd Ste 5 & 6, Brandon, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at Nancy Simons Ling MD PA on 08/06/2026. The laboratory was surveyed under 42 CFR Part 493 CLIA requirements. Standard deficiencies cited are as follows:
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on observation, interview, and review safety data sheets (SDS), the laboratory failed to ensure protection from chemical hazards used for Histopathology testing of Hematoxylin and Eosin (H&E) stain from 06/17/2024 to 08/06/2026. Findings: 1. During a tour of the laboratory on 08/06/2026 at 10:25 AM, no fume hood was observed to provide protection from respiratory chemical hazards of the reagents used for H & E testing. 2. The SDS sheets for Eosin Solution, Reagent Alcohol 100%, and Reagent Alcohol 95%, all included hazard statements regarding inhalation precautions. 3. The Laboratory Policy Manual last approved by the Laboratory Director 08/25/2025 included a document titled OSHA with a list of Personal Protective/Safety Equipment within the laboratory-item #6-Fume Hood. 4. The Testing Person B confirmed on 08/06/2026 at 10:25 AM there was no hood or any other method to ensure respiratory protection from chemical hazards used for H & E staining.