Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	10D0957153	07/10/2018
Name of Provider or Supplier	**Street Address, City, State**	
Alfredo D Fernandez Md Pa D/B/A	2426 S Tamiami Trl, Sarasota, FL	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on observation and interview with the Histology Technician, the laboratory failed to dispose of Eosin Y, GILL III Hematoxylin, Histo-Clear, and 100% Reagent Alcohol for 2 out of 2 (2016-2018) years reviewed. Findings Included: Observation of reagents in the flammable cabinet on 7/10/2018 at 9:45 AM revealed the labels on the Eosin Y, GILL III Hematoxylin, Histo-Clear, and 100% Reagent Alcohol stated the contents/container be disposed at an approved waste disposal plant. (Photographic evidence obtained). On 07/10/18 at 9:45 AM, the Histology Technician stated that all reagent waste was disposed of down the drain of the sink with copious amounts of water.