

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1010469	(X3) Date Survey Completed 09/17/2026
Name of Provider or Supplier Monica K Bedi Md Pa	Street Address, City, State 3830 Bee Ridge Rd Ste 200, Sarasota, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at Monica K Bedi PA on 9 /17/2026. The laboratory was surveyed under 42 CFR Part 493 CLIA requirements. Standard deficiencies cited are as follows:
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on observation, interview, and review safety data sheets (SDS), the laboratory failed to ensure protection from chemical hazards used for Histopathology testing of Hematoxylin and Eosin (H&E) stain from 06/28/24 to 9/17/26. Findings: 1. During a tour of the laboratory on 9/17/2026 at 10:55 AM, the fume hood in the laboratory to provide protection from respiratory chemical hazards was observed not used for H & E testing for Mohs staining. 2. The SDS sheets for Eosin Solution, Reagent Alcohol 100%, and Reagent Alcohol 95%, all included hazard statements regarding inhalation precautions. 3. The Laboratory Policy Manual last approved by the Laboratory Director 10/06/2025 included a document titled Safety Policy indicating the Laboratory Director would ensure that the laboratory is a safe working environment to include all hazards. 4. Histotech A stated on 9/17/2026 at 10:55 AM the hood in the laboratory was used for the staining of frozen H&E staining but not for the Mohs staining to ensure respiratory protection from chemical hazards used for H & E staining.