Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	10D2039980	09/16/2019
Name of Provider or Supplier	**Street Address, City, State**	
Florida Medical Clinic Pa	2100 Via Bella Blvd Ste 101, Land O Lakes, FL	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at Florida Medical Clinic PA on 09/16/19. The laboratory is not in compliance with 42 CFR Part 493, Requirements for Laboratories. The following is a description of the standard level deficiencies:
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on observation and interview with the Lab Manager the laboratory failed to dispose of Reagent Alcohol, Eosin, and Xylene substitute per the manufacturers' instructions for at least 2 of 2 years reviewed (2017-2019). Findings Included: During a tour of the laboratory on 09/16/19 at 12:00 PM it was observed that there wasn't a chemical waste container. Review of the Reagent Alcohol (Lot-377157) label revealed to "Dispose of contents/container to an approved waste disposal plant." Photographic evidence was obtained. Review of the Alcoholic Eosin Y 515 (Lot-041218) label revealed to "Dispose of container contents to approved disposal site in accordance with local and national regulations." Photographic evidence was obtained. Review of the Xylene Substitute (Lot-481382) label revealed to "Dispose of contents /container to an approved waste disposal plant." Photographic evidence was obtained. Interview with the Lab Manager on 09/16/19 at 12:40 PM revealed that the 3 chemicals (Reagent Alcohol, Eosin, and Xylene substitute) were washed down the drain and not taken to a waste disposal plant.