Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number** 10D2152309	**(X3) Date Survey Completed** 05/15/2020
Name of Provider or Supplier Tampa Bay Dermatology Llc	**Street Address, City, State** 2727 W Dr Martin Luther King Jr Dr Ste 570, Tampa, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	**Summary Statement of Deficiencies**
D0000	An announced CLIA recertification survey was conducted at Tampa Bay Dermatology on 05/15/2020. The laboratory is not in compliance with 42 CFR Part 493, Requirements for Laboratories. The following is a description of the standard level deficiencies:
D5781	CORRECTIVE ACTIONS CFR(s): 493.1282(b)(1) (b) The laboratory must document all corrective actions taken, including actions taken when any of the following occur: (b)(1) Test systems do not meet the laboratory's verified or established performance specifications, as determined in 493.1253(b), which include but are not limited to-- (b)(1)(i) Equipment or methodologies that perform outside of established operating parameters or performance specifications; (b)(1)(ii) Patient test values that are outside of the laboratory's reportable range of test results for the test system; and (b)(1)(iii) When the laboratory determines that the reference intervals (normal values) for a test procedure are inappropriate for the laboratory's patient population. This STANDARD is not met as evidenced by: Based on record review and staff interview, the facility failed to document corrective action when the room temperature of the laboratory, where the cryostats were located, was out of range for 18 days from January 2019 to May 14, 2020. Findings included: The record review of the "Room Temperature" logs showed the acceptable temperature range was 68-76 degrees Fahrenheit (F). The following temperatures were documented: 01/15/2019 - 78 degrees F 01/28/2019 - 60 degrees F 04/12/2019 - 77 degrees F 05/23/2019 - 78 degrees F 06/04/2019 - 77 degrees F 06/18/2019 - 77 degrees F 06/20/2019 - 79 degrees F 07/01/2019 - 79 degrees F 07/02/2019 - 78 degrees F 07/03/2019 - 77 degrees F 07/12/2019 - 78 degrees F 07/16/2019 - 77 degrees F 08/01/2019 - 78 degrees F 08/10/2019 - 82 degrees F 09/27/2019 - 66

	degrees F 11/06/2019 - 80 degrees F 01/21/2020 - 67 degrees F 01/22/2020 - 65 degrees F Interview on 05/15/2020 at 10:20 am with the Medical Assistant (MA) confirmed the temperatures were documented out of range. The MA stated that the laboratory had brought in fans to try to cool off the laboratory when temperatures exceeded the temperature range and eventually had the windows in the laboratory tinted. The MA stated that when the temperatures were too cold, the laboratory closed the door to increase the temperature of the laboratory. These corrective actions were not documented, and the room temperature was not observed and documented after the corrective actions were taken.