

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D2153803	(X3) Date Survey Completed 09/01/2026
Name of Provider or Supplier St Petersburg Dermatology	Street Address, City, State 1530 Dr Mlk Jr St N, Saint Petersburg, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at St Petersburg Dermatology on 09/01/2026. The laboratory was surveyed under 42 CFR Part 493 CLIA requirements. Standard deficiencies cited are as follows:
D6011	LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(e)(2) (e)(2) provide a safe environment in which employees are protected from physical, chemical, and biological hazards; This STANDARD is not met as evidenced by: Based on observation, record review, and interview the Laboratory Director failed to ensure employees were protected from chemical hazards for two of two years 09/2024 - 09/2026 for the subspecialty of Histopathology. Findings included: 1. A tour was conducted of the laboratory beginning at 1:05 p.m. on 09/01/2026. A flammable cabinet was observed to contain Xylene Substitute and Hematoxylin Stain, Harris Modified reagents. The slide staining area did not have a fume hood. Photographic evidence was taken. 2. The Safety Data Sheet (SDS) for both reagents were reviewed. The SDS for the Hematoxylin stain had a revision date of 06/15/2015. The SDS for the Xylene Substitutue had a revision date of 12/08/2015. Both reagents were considered hazardous per the 2012 OSHA Hazard Communication Standard (29 CFR 1910.1200) and harmful if inhaled. 3. The Lab Director was interviewed on 09/01 /2026 at approximately 4:05 p.m. They confirmed the laboratory did not have a fume hood to mitigate exposure to the reagents.