Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number** 11D1100175	**(X3) Date Survey Completed** 04/11/2019
Name of Provider or Supplier Wmg Urgent Care Cherokee Health Park	**Street Address, City, State** 1120 Wellstar Way, Suite 105, Holly Springs, GA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	**Summary Statement of Deficiencies**
D0000	A Clinical Laboratory Improvement Amendments (CLIA) recertification survey was completed on April 11, 2019. The laboratory was not in compliance with applicable CLIA requirements found at 42 CFR 493.1 through 42 CFR 493.1780. The following deficiencies were cited:
D6054	TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9) The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year. This STANDARD is not met as evidenced by: Based on Personnel competency records review and an interview with the Technical Consultant (TC), (TP # 3 CMS 209), the (TC) failed to perform annual competencies on two physicians performing PPM Microscopy. Findings include: 1. Annual competencies were not performed on the two physicians (TP #8 and #9 CMS 209) performing PPM microscopy in 2017 and 2018. 2. An interview with the Technical Consultant (TP #3 CMS 209) on April 11, 2019 in the review room at approximately 11:45 a.m. confirmed annual competencies were not performed on the physicians by the TC in 2017 and 2018.