Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number** 11D2064789	**(X3) Date Survey Completed** 01/30/2019
Name of Provider or Supplier St Joseph's Candler Urgent Care Centers	**Street Address, City, State** 107 Canal Street, Pooler, GA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	**Summary Statement of Deficiencies**
D0000	A Clinical Laboratory Improvement Amendments (CLIA) recertification survey was completed on January 30, 2019. The laboratory was not in compliance with applicable CLIA requirements found at 42 CFR 493.1 through 42 CFR 493.1780. The following deficiency was cited:
D6046	TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8) (b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently. This STANDARD is not met as evidenced by: Based on review of 2018 personnel competency assessment records and staff interview , the laboratory director/technical consultant failed to include the six required competency assessment criteria when evaluating competency on testing personnel for testing performed on the Medonic M Series Hematology analyzer . The findings include: 1. Review of testing personnel competency assessment records for 2018 on 9 of 9 testing personnel revealed the assessment did not include the six competency assessment criteria required by CLIA. 2. Interview with the office administrator and testing personnel # 9 (see CMS 209) in the administrator's office on January 30, 2019 at approximately 1:00 PM confirmed 2018 annual competency assessments did not contain the six criteria required by CLIA.