Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 17D2180550	(X3) Date Survey Completed 04/11/2024
Name of Provider or Supplier Manhattan Medical Group, Llc	**Street Address, City, State** 202 Research Drive, Manhattan, KS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6045	TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(7) (b) The technical consultant is responsible for-- (b)(7) Identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; This STANDARD is not met as evidenced by: Based on the review of the CMS 209, 2023 training records, test report records, and interview with Testing Personnel (TP) #1, the technical consultant failed to ensure one of five testing personnel received adequate training prior to performing patient testing. Findings: 1. Review of the CMS 209 personnel form revealed two new TP since last survey on 8/22/22. 2. Request was made for the training documentation on the new TP. No documentation of training was provided on TP #5 at the time of survey. 3. Test report records revealed 73 non-waived test results on seven patients were reported from 2/16/23 to 8/7/23. 4. Interview with TP #1 on 4/11/24 at 3:30 p.m. confirmed, the technical consultant failed to ensure one of five testing personnel received adequate training prior to performing patient testing.