

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 20D2110230	(X3) Date Survey Completed 09/16/2026
Name of Provider or Supplier Intermed Mohs Lab - Dermatology	Street Address, City, State 100 Foden Rd, West Suite 203, South Portland, ME	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5781	CORRECTIVE ACTIONS CFR(s): 493.1282(b)(1) (b) The laboratory must document all corrective actions taken, including actions taken when any of the following occur: (b)(1) Test systems do not meet the laboratory's verified or established performance specifications, as determined in 493.1253(b), which include but are not limited to-- (b)(1)(i) Equipment or methodologies that perform outside of established operating parameters or performance specifications; (b)(1)(ii) Patient test values that are outside of the laboratory's reportable range of test results for the test system; and (b)(1)(iii) When the laboratory determines that the reference intervals (normal values) for a test procedure are inappropriate for the laboratory's patient population. This STANDARD is not met as evidenced by: Based on record review and staff interview, the laboratory failed to document corrective actions when the temperature of the Cryostat was outside of its established operational temperature range. Findings include: 1. Record review on 9/16/2026 of the laboratory's 2025 and 2026 to date Cryostat temperature records revealed: a. The established operating temperature range was -21C to -30C. b. In 2025, the recorded temperature was outside the established operating range on 65 of 158 working days, with no documented corrective action for the out-of-range temperatures. c. From January 1, 2026 through the date of survey, 9/16/2026, the recorded temperature was outside the established operating range on 17 of 114 working days, with no documented corrective action for the out-of-range temperatures. 2. Record review on 9/16/2026 of the laboratory's 'Cryostat Maintenance' policy revealed, "The cryostats should be maintained between -21C to -30C for best Mohs sectioning. Any variance out of range will be recorded and reported to the supervisor immediately. If the range variance cannot be repaired, the console will not be used until serviced." 3. Staff interview on 9/16/2026 at 10:50 AM with the Practice Manager for Specialty Services confirmed the above findings.