Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	22D1028178	06/26/2023
Name of Provider or Supplier	**Street Address, City, State**	
Internal Medicine Physicians Of The North Shore	27 Centennial Dr, Peabody, MA	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A CLIA recertification survey was conducted for the Internal Medicine Physicians of the North Shore laboratory pursuant to the Clinical Laboratory Improvement Amendments (CLIA) of 1988 and CLIA regulations at 42 CFR 493.
D6053	TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9) The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least semiannually during the first year the individual tests patient specimens. This STANDARD is not met as evidenced by: . Based on personnel competency record review and interview with the Technical Consultant (TC) on 6/26//2023, the TC failed to evaluate and document the performance of individuals responsible for moderate complexity testing at least semiannually during the first year the individual tested patient specimens as evidenced by the following: The surveyor asked for the personnel competency records for review. The review revealed that a semiannual competency evaluation was not performed and documented for one (1) of the newly hired testing persons (TP) in their first year of performing moderate complexity testing. The TC confirmed in an interview on 6/26/2023 at 9:47 AM that the TC failed to perform and document semiannual competency evaluations for one (1) newly hired TP in their first year of performing moderate complexity testing. The laboratory performs 606 virology tests, 19 general immunology tests, 161,676 chemistry tests, and 42,696 hematology tests annually.