Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	24D0398942	09/24/2026
Name of Provider or Supplier	**Street Address, City, State**	
Minnesota Urology, Pa	6025 Lake Road, Suite 200, Woodbury, MN	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The Minnesota Urology, PA laboratory was found to be out of compliance with the regulations of the Clinical Laboratory Improvement Amendments of 1988 (42 C.F.R. part 493) upon completion of the recertification survey completed on September 24, 2026. The following standard-level deficiencies were cited: 493.1451 Technical supervisor responsibilities .
D6125	TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(8)(v) (b)(8)(v) Assessment of test performance through testing previously analyzed specimens, internal blind testing samples or external proficiency testing samples; and This STANDARD is not met as evidenced by: . Based on document review and interview with laboratory personnel, the Technical Supervisor (TS) failed to evaluate testing performance through blind sample analysis in the initial and semiannual competency assessments for one of four testing personnel in 2025. Findings are as follows: 1. The laboratory performed Hematology, Microbiology, Urinalysis, and Chemistry testing as confirmed by the General Supervisor during a tour of the laboratory at 10:07 am on 9/23/26. 2. The laboratory was required to evaluate test performance through blind sampling as defined in the Personnel Competency procedure provided by the laboratory on the date of survey. 3. The initial and semiannual competency assessments performed in 2025 for testing personnel 4 did not include documentation of blind sample analysis for all Hematology, Microbiolgy, Urinalysis, and Chemistry test systems. 4. In an interview at 11:22 am on 9/23/26, the TS confirmed the above findings. .
D6126	TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(8)(vi) (b)(8)(vi) Assessment of problem-solving skills; and

	This STANDARD is not met as evidenced by: . . Based on document review and interview with laboratory personnel, the Technical Supervisor (TS) failed to assess problem solving skills in the initial and semiannual competency assessments for one of four testing personnel in two of four areas of testing in 2025. Findings are as follows: 1. The laboratory performed Hematology, Microbiology, Urinalysis, and Chemistry testing as confirmed by the General Supervisor during a tour of the laboratory at 10:07 am on 9/23/26. 2. The laboratory was required to assess problem solving skills in all areas of testing as defined in the Personnel Competency procedure provided by the laboratory on the date of survey. 3. The initial and semiannual competency assessments performed in 2025 for testing personnel 4 included problem solving skills assessment for all test systems in Urinalysis and Mirobiology. Comptetency assessment documents did not include evidence of problem solving skills assessment for Hematology and Chemistry test systems. 4. In an interview at 11:22 am on 9/23/26, the TS confirmed the above findings. .