Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 33D2074146	(X3) Date Survey Completed 06/28/2018
Name of Provider or Supplier Gold Coast Medical Pc	**Street Address, City, State** 121 Eileen Way, Syosset, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5407	PROCEDURE MANUAL CFR(s): 493.1251(d) Procedures and changes in procedures must be approved, signed, and dated by the current laboratory director before use. This STANDARD is not met as evidenced by: Based on a surveyor's review of the laboratory's procedure manual and an interview and confirmed with the laboratory director, the laboratory failed to have a procedure manual that is up-to-date and accurate and the laboratory director failed to approve (sign and date) the laboratory procedure manual. FINDINGS: 1. The procedure manual was last signed and dated on January 15, 2016. 2. The current procedure manual still lists the previous technical component laboratory's name, EastGene. The laboratory's current technical component laboratory is PathGenix Diagnostics.