Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 38D2158457	(X3) Date Survey Completed 11/24/2020
Name of Provider or Supplier Reproductive Medicine Laboratory Southside	**Street Address, City, State** 12115 Sw 70th Ave Suite 101, Portland, OR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A survey of the Reproductive Medicine Laboratory South located at 12115 SW 70th Avenue, Suite 101, Portland, OR. 97223 was conducted on November 24, 2020. The Laboratory was found to be in substantial compliance with the CLIA regulations (42 CFR, Part 493 effective April 24, 2003). No deficiencies were cited.