Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number** 39D1033904	**(X3) Date Survey Completed** 02/22/2023
Name of Provider or Supplier Geisinger Woodbine Lane	**Street Address, City, State** 16 Woodbine Lane, Danville, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	**Summary Statement of Deficiencies**
D5449	CONTROL PROCEDURES CFR(s): 493.1256(d)(3)(ii)(g) Unless CMS Approves a procedure, specified in Appendix C of the State Operations Manual (CMS Pub. 7), that provides equivalent quality testing, the laboratory must-- At least once a day patient specimens are assayed or examined perform the following for-- Each qualitative procedure, include a negative and positive control material; (g) The laboratory must document all control procedures performed. This STANDARD is not met as evidenced by: Based on review of the laboratory's dermatology microscopy quality control (QC) records and interview with technical consultant #1 (TS), the laboratory failed to document a negative and positive control material each day of patient testing for mycology and parasitology microscopic examinations performed in January 2023. Findings Include: 1. On the day of the survey, 02/22/2023 at 11:44 am, a review of the dermatology microscopy QC records revealed the laboratory did not document a negative and positive control material each day of patient testing for mycology and parasitology microscopic slide examinations performed in January 2023 for the following: - 1 of 9 days of patient testing in January 2023 (01/13/2023) 2. The laboratory performed 1 mycology and 1 parasitology slide examination on 01/13 /2023. 3. TC#1 confirmed the findings above on 02/22/2023 around 01:00 pm.