

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D1087365	(X3) Date Survey Completed 09/02/2026
Name of Provider or Supplier Nashville Pain And Wellness Center Pllc	Street Address, City, State 7105 Ramsey Way, Dickson, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5435	MAINTENANCE AND FUNCTION CHECKS CFR(s): 493.1254(b)(2) (b)(2)(i) Define a function check protocol that ensures equipment, instrument, and test system performance that is necessary for accurate and reliable test results and test result reporting. (b)(2)(ii) Perform and document the function checks, including background or baseline checks, specified in paragraph (b)(2)(i) of this section. Function checks must be within the laboratory's established limits before patient testing is conducted. This STANDARD is not met as evidenced by: Based on laboratory observation, a review of the laboratory's policy titled "Reagent Handling and Storage," a review of the laboratory's calibration records, and staff interview, the laboratory failed to follow its policy by failing to calibrate two of two pipettes used to prepare patient specimens for urine toxicology testing when due in January of 2026. The findings included: 1. Laboratory observation on 09/01/26 at 8:30 a.m. revealed two Eppendorf Research pipettes (20 - 200 uL, serial number P26321F and 100 - 1000 uL, serial number L20704F) used to prepare patient specimens for urine toxicology testing. 2. A review of the laboratory's policy titled "Reagent Handling and Storage" revealed "maintenance on the pipettes is conducted annually." 3. A review of the laboratory's calibration records revealed that the laboratory's pipettes were last calibrated on 01/22/2025. 4. The Technical Consultant confirmed the findings during an interview on 09/01/2026 at 11:20 a.m.