Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number** 45D1075228	**(X3) Date Survey Completed** 01/06/2021
Name of Provider or Supplier South Texas Clinical Laboratory	**Street Address, City, State** 418 S 6th Street, Kingsville, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	**Summary Statement of Deficiencies**
D5785	CORRECTIVE ACTIONS CFR(s): 493.1282(b)(3) (b) The laboratory must document all corrective actions taken, including actions taken when any of the following occur: (b)(3) The criteria for proper storage of reagents and specimens, as specified under 493.1252(b), are not met. This STANDARD is not met as evidenced by: Based on review of the laboratory's room temperature records from December 2020 and staff interview, it was revealed the laboratory's failed to have documentation of performing corrective action when documented temperatures were not within the laboratory's defined acceptability ranges. The findings were: 1. A review of the laboratory's room temperature records from December 2020 revealed the laboratory's acceptable room temperature range was 21 - 25C. 2. Further review of the temperature records from December 2020 indentified the following days where the documented room temperature was outside the laboratory's defined acceptable range: 12/01 20.3C 12/03 20.8C 12/05 20.4C 12/06 20.6C 3. The laboratory was asked to provide documentation of performing corrective actions on the identified days. No documentation was provided. 4. An interview with the general supervisor on 01/05 /2021 at 1100 hours in the laboratory - after his review of the records - confirmed the findings.