Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number** 45D2047065	**(X3) Date Survey Completed** 03/11/2021
Name of Provider or Supplier B Pediatrics	**Street Address, City, State** 4503 Texas Boulevard, Texarkana, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	**Summary Statement of Deficiencies**
D0000	Based on a proficiency testing desk review survey performed on March 11, 2021, the laboratory was found to be out of compliance based on the following CONDITION LEVEL DEFICIENCIES: D2016 - 42 C.F.R. 493.803 Condition: Successful participation D2017 - 42 C.F.R. 493.807 Condition: Reinstatement of laboratories performing non-waived testing D6000 - 42 C.F.R. 493.1403 Condition: Laboratory Director, moderate complexity
D2016	SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c) (a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history. This CONDITION is not met as evidenced by: Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency

	Institute proficiency testing records, the facility failed to achieve successful performance in three out of four consecutive testing events for the specialty of Hematology, resulting in unsuccessful performance in the specialty of Hematology. Refer to D2130.
D2017	REINSTATEMENT OF NONWAIVED LABORATORIES CFR(s): 493.807(a)(b) (a) If a laboratory's certificate is suspended or limited or its Medicare or Medicaid approval is cancelled or its Medicare or Medicaid payments are suspended because it fails to participate successfully in proficiency testing for one or more specialties, subspecialties, analyte or test, or voluntarily withdraws its certification under CLIA for the failed specialty, subspecialty, or analyte, the laboratory must then demonstrate sustained satisfactory performance on two consecutive proficiency testing events, one of which may be on site, before CMS will consider it for reinstatement for certification and Medicare or Medicaid approval in that specialty, subspecialty, analyte or test. (b) The cancellation period for Medicare and Medicaid approval or period for suspension of Medicare or Medicaid payments or suspension or limitation of certification under CLIA for the failed specialty, subspecialty, or analyte or test is for a period of not less than six months from the date of cancellation, limitation or suspension of the CLIA certificate. This CONDITION is not met as evidenced by: Based on desk review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute (API) proficiency testing records, the facility failed to achieve successful performance in three out of four consecutive testing events for the analyte specialty of Hematology, resulting in a non-initial proficiency testing failure in the specialty of Hematology. The findings included: 1. The laboratory received the following unsatisfactory scores (satisfactory is 80% or greater) for the specialty of Hematology in three of four consecutive testing events in 2019 and 2020. 2019 API 3rd event - Hematology Score: 0 2020 API 2nd event - Hematology Score: 0 2020 API 3rd event - Hematology Score: 0 2. For the 3rd event of 2019, the facility failed to participate for the specialty of hematology, including the following analytes: 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0 For the 2nd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0 For the 3rd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0
D2123	HEMATOLOGY CFR(s): 493.851(c) Failure to participate in a testing event is unsatisfactory performance and results in a score of 0 for the testing event. Consideration may be given to those laboratories failing to participate in a testing event only if-- (1) Patient testing was suspended during the time frame allotted for testing and reporting proficiency testing results; (2) The laboratory notifies the inspecting agency and the proficiency testing program

	within the time frame for submitting proficiency testing results of the suspension of patient testing and the circumstances associated with failure to perform tests on proficiency testing samples; and (3) The laboratory participated in the previous two proficiency testing events. This STANDARD is not met as evidenced by: Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute (API) proficiency testing records, the facility failed to participate in three out of four consecutive testing events for the specialty of Hematology, resulting in unsuccessful performance in the specialty of Hematology. The findings included: 1. Based on review of the American Proficiency Institute (API) proficiency evaluation reports, the laboratory failed to participate in the following events between 2019 and 2020: For the 3rd event of 2019, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY FAILED TO PARTICIPATE 0765 CELL I.D. OR WBC DIFF FAILED TO PARTICIPATE 0785 HCT (NON-WAIVED) FAILED TO PARTICIPATE 0795 HGB (NON-WAIVED) FAILED TO PARTICIPATE 0805 WBC FAILED TO PARTICIPATE 0815 PLATELETS FAILED TO PARTICIPATE For the 2nd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY FAILED TO PARTICIPATE 0765 CELL I.D. OR WBC DIFF FAILED TO PARTICIPATE 0785 HCT (NON-WAIVED) FAILED TO PARTICIPATE 0795 HGB (NON-WAIVED) FAILED TO PARTICIPATE 0805 WBC FAILED TO PARTICIPATE 0815 PLATELETS FAILED TO PARTICIPATE For the 3rd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY FAILED TO PARTICIPATE 0765 CELL I.D. OR WBC DIFF FAILED TO PARTICIPATE 0785 HCT (NON-WAIVED) FAILED TO PARTICIPATE 0795 HGB (NON-WAIVED) FAILED TO PARTICIPATE 0805 WBC FAILED TO PARTICIPATE 0815 PLATELETS FAILED TO PARTICIPATE 2. Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile, the laboratory received a score of 0 percent for each event the laboratory failed to participate: For the 3rd event of 2019, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY Score: 0 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0 For the 2nd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY Score: 0 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0 For the 3rd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY Score: 0 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0
D2130	HEMATOLOGY CFR(s): 493.851(f) Failure to achieve satisfactory performance for the same analyte in two consecutive events or two out of three consecutive testing events is unsuccessful performance.

	This STANDARD is not met as evidenced by: Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute (API) proficiency testing records, the facility failed to achieve satisfactory performance in three out of four consecutive testing events for the analytes CELL I.D. OR WBC DIFF, HCT (NON-WAIVED), HGB (NON-WAIVED), WBC, PLATELETS , resulting in unsuccessful performance in the specialty of Hematology. The findings included: 1. Based on review of the American Proficiency Institute (API) proficiency evaluation reports, the laboratory failed to participate in the following events between 2019 and 2020, resulting in a score of 0 percent: For the 3rd event of 2019, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY Score: 0 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0 For the 2nd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY Score: 0 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0 For the 3rd event of 2020, the facility failed to participate for the specialty of hematology, including the following analytes: 0760 HEMATOLOGY Score: 0 0765 CELL I.D. OR WBC DIFF Score: 0 0785 HCT (NON-WAIVED) Score: 0 0795 HGB (NON-WAIVED) Score: 0 0805 WBC Score: 0 0815 PLATELETS Score: 0
D2131	HEMATOLOGY CFR(s): 493.851(g) Failure to achieve an overall testing event score of satisfactory performance for two consecutive testing events or two out of three consecutive testing events is unsuccessful performance. This STANDARD is not met as evidenced by: Based on desk review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute (API) proficiency testing records, the facility failed to achieve successful performance in three out of four consecutive testing events for the analyte specialty of Hematology, resulting in a non-initial proficiency testing failure in the specialty of Hematology. The findings included: 1. The laboratory received the following unsatisfactory scores (satisfactory is 80% or greater) for the specialty of Hematology in three of four consecutive testing events in 2019 and 2020. 2019 API 3rd event - Hematology 0% 2020 API 2nd event - Hematology 0% 2020 API 3rd event - Hematology 0%
D6000	MODERATE COMPLEXITY LABORATORY DIRECTOR CFR(s): 493.1403 The laboratory must have a director who meets the qualification requirements of 493. 1405 of this subpart and provides overall management and direction in accordance with 493.1407 of this subpart. This CONDITION is not met as evidenced by:

	Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute proficiency testing records, the laboratory director failed to ensure successful participation in a HHS approved proficiency testing program for the specialty of Hematology. Refer to D6016.
D6016	LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(e)(4)(i) The laboratory director is responsible for the overall operation and administration of the laboratory, including the employment of personnel who are competent to perform test procedures, and record and report test results promptly, accurate, and proficiently and for assuring compliance with the applicable regulations. (e) The laboratory director must-- (e)(4)(i) Ensure that the proficiency testing samples are tested as required under Subpart H of this part; This STANDARD is not met as evidenced by: Based on desk review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute (API) proficiency testing records, the laboratory director failed to ensure successful participation in a HHS approved proficiency testing program for specialty of Hematology. Refer to D2130.