Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number** 45D2112931	**(X3) Date Survey Completed** 09/10/2025
Name of Provider or Supplier Advanced Dermatology& Skin Cancer Institute	**Street Address, City, State** 4709 66th Street, Lubbock, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	**Summary Statement of Deficiencies**
D0000	An offsite revisit survey was completed on September 25, 2025 for deficiencies cited on September 10, 2025. All deficiencies have been corrected. The facility is in compliance with 42 CFR Part 493, Requirements for Laboratories. 45469 The laboratory was found to be in compliance with 42 CFR Part 493, Requirements for Laboratories as a result of a recertification survey completed on September 10, 2025.
D5417	TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(d) (d) Reagents, solutions, culture media, control materials, calibration materials, and other supplies must not be used when they have exceeded their expiration date, have deteriorated, or are of substandard quality. This STANDARD is not met as evidenced by: Based upon observations, patient test records and interview of facility personnel, the laboratory failed to ensure expired EosinY stain was not used to stain 6 patient samples between September 6 and September 9, 2025. The findings included: 1. Observations made on September 10, 2025 at 09:32 found one partial container of Mercedes Scientific EosinY stain lot 2323725 expiration 2025-09-05 in the flammable cabinet. 2. Review of patient test records found the laboratory tested 6 patient specimens between September 6 and September 9, 2025 as follows: M25-249 M25-250 M25-251 M25-252 M25-253 M25-254 3. During interview of the histotechnician conducted September 10, 2025 at 9:40 AM, she confirmed the expired stain was used to stain the 6 specimens.