Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 46D0525866	(X3) Date Survey Completed 01/26/2023
Name of Provider or Supplier Southwest Skin And Cancer	**Street Address, City, State** 383 S 300 E, St George, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5209	PERSONNEL COMPETENCY ASSESSMENT POLICIES CFR(s): 493.1235 As specified in the personnel requirements in subpart M, the laboratory must establish and follow written policies and procedures to assess employee and, if applicable, consultant competency. This STANDARD is not met as evidenced by: Based on record review and interview with the laboratory director, the laboratory failed to establish a written policy to assess personnel competency for mid-level practitioners who conducted (potassium hydroxide) KOH testing since the last survey on October 28, 2019. Findings include: 1. Review of laboratory policies and procedures revealed the laboratory failed to establish and perform competency assessment for three of three testing personnel who were mid-level practitioners conducting KOH testing. 2. On January 26, 2023 at approximately 10:00 AM, the laboratory director confirmed there was no competency assessment policy established or performed for mid-level practitioners conducting KOH testing.