

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 46D2108732	(X3) Date Survey Completed 08/17/2026
Name of Provider or Supplier Sterling Urgent Care	Street Address, City, State 630 E 1400 N #150, Logan, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2007	TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1) (b)(1) The samples must be examined or tested with the laboratory's regular patient workload by personnel who routinely perform the testing in the laboratory, using the laboratory's routine methods. This STANDARD is not met as evidenced by: Based on record review and interview with the Testing Personnel (TP#1), the laboratory failed to perform proficiency testing (PT) using the laboratory's routine methods by not having all testing personnel (TP) perform PT. The laboratory performed approximately 511 hematology tests a year. Findings include: 1. Review of CMS-209 Laboratory Personnel Form showed the laboratory had 9 TP that performed hematology testing. 2. PT record review revealed that TP #1 performed PT for 3 out of 3 API Hematology PT events in 2025, 2 out of 2 API Hematology PT events in 2026. 3. In an interview on 08/17/2026 at 11:50 AM, TP#1 confirmed that not all hematology TP performed PT.