

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 51D0694471	(X3) Date Survey Completed 08/27/2026
Name of Provider or Supplier Cabin Creek Health Center	Street Address, City, State 5722 Cabin Creek Road, Dawes, WV	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A routine recertification survey was conducted at Cabin Creek Health Center on August 27, 2026, by the West Virginia Office of Laboratory Services. The laboratory was assessed for compliance with 42 CFR 493, Requirements for Laboratories and noncompliance was found. Specific deficiencies are cited below.
D6064	TESTING PERSONNEL QUALIFICATIONS CFR(s): 493.1423(a) Each individual performing moderate complexity testing must-- (a) possess a current license issued by the State in which the laboratory is located, if such licensing is required; and This STANDARD is not met as evidenced by: Based on review of laboratory CMS 209 form, current test menu, testing personnel (TP) files, WV LAB-PLUS license verification database, patient results from the GEM Premier 5000 analyzer, and interview with the laboratory director, one of three testing personnel (TP3) did not have a Clinical Laboratory Practitioner (CLP) license as required by the WV CLP Licensure Rule, 64 CSR 57 from June 6, 2025, thru date of survey. Findings: 1. Review of the 7/30/2026 CMS 209 form revealed three listed TP for the respiratory therapy laboratory. 2. Review of the current test menu for moderate complexity testing identified the following blood gas and oximetry analytes: pH, pCO2, pO2, carboxyhemoglobin, hemoglobin, methemoglobin, and oxyhemoglobin. 3. Review of TP files revealed the following certifications and licensure: TP1 respiratory therapist with current licensure LRTC01635 TP2 respiratory therapist with current licensure LRTR0948 TP3 certified medical assistant, no respiratory therapist or CLP license WV Clinical Laboratory Practitioner (CLP) licensure rule at 64 CSR 57 states that a current license is required for any individual performing moderately complex testing, unless otherwise exempt. Individuals licensed as Respiratory Therapists by the West Virginia Board of Respiratory Care are exempt from the CLP licensure rule under 57-1.6.3.c. if testing is limited to blood

gases and oximetry. 4. Review of WV LAB-PLUS license verification database identified TP3 had no history of holding a CLP license. 5. Review of a 8/11/26 blood gas and oximetry report from the GEM 5000 Premier (patient A) identified results ran on the analyzer by TP3. 6. During an interview, 8/27/26 at 9:15 AM, the laboratory director verified the lack of required CLP licensure for TP3 from June 2025 thru date of survey. 7. An exit interview with the laboratory director and laboratory manager, 8/27/26 at 10:15 AM, confirmed the finding.