Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 65D2137458	(X3) Date Survey Completed 09/27/2021
Name of Provider or Supplier Diagnostic Laboratory Services - Amc-1	**Street Address, City, State** 1244 N Marine Corps Dr, Tamuning, GU	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on observation of the phlebotomy area located within the laboratory and interview with the technical supervisor (TS) #1, the laboratory failed to provide a safe environment in which employees and patients are protected from physical, chemical, and biological hazards. Findings: 1. Observation of the phlebotomy area located directly within the small laboratory showed one phlebotomy chair with patients having their blood drawn. The phlebotomy chair was directly across from the centrifuge and Sysmex hematology analyzer. The phlebotomy chair was located next to the computer and patient reports. The phlebotomy procedures were occurring while laboratory testing personnel were analyzing patient specimens. 2. Interview with the TS #1 on September 27, 2021 at 11:00 AM confirmed the laboratory failed to ensure laboratory personnel and patients were protected from physical, chemical and biohazardous materials.