

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 01D2029146	(X3) Date Survey Completed 12/21/2022
Name of Provider or Supplier Compass Urgent Care, Llc	Street Address, City, State 9985 Airport Blvd, Mobile, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a review of personnel records and an interview with the Laboratory Manager, the Technical Consultant failed to assess the competency of Testing Personnel listed on the Form CMS-209 (Laboratory Personnel Report) for the Abbott i-Stat testing system. This was noted for 30 out of 30 Testing Personnel who had competency assessments completed from 04/08/2021 to the date of the current survey (12/21/2022). The findings include: 1. A review of Testing Personnel records revealed the competency assessments for the Abbott i-Stat were completed and signed by the Laboratory Manager. The surveyor did not observe a delegation form for the Laboratory Manager to take on this responsibility of the Technical Consultant. 2. During an interview at 3:45 PM on 12/21/2022, the Laboratory Manager confirmed the above findings.</p>