

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 03D0680709	(X3) Date Survey Completed 04/23/2025
Name of Provider or Supplier Honorhealth Cancer Care	Street Address, City, State 3621 N Wells Fargo Avenue, Scottsdale, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5805	<p>TEST REPORT CFR(s): 493.1291(c)</p> <p>(c) The test report must indicate the following: (c)(1) For positive patient identification, either the patient's name and identification number, or a unique patient identifier and identification number. (c)(2) The name and address of the laboratory location where the test was performed. (c)(3) The test report date. (c)(4) The test performed. (c)(5) Specimen source, when appropriate. (c)(6) The test result and, if applicable, the units of measurement or interpretation, or both. (c)(7) Any information regarding the condition and disposition of specimens that do not meet the laboratory's criteria for acceptability.</p> <p>This STANDARD is not met as evidenced by: Based on review of patient test reports and interview with the Technical Consultant (TC-1), 3 out of 3 test reports failed to include the correct laboratory address where the testing was performed. Findings include: 1. The laboratory performs patient testing in the specialty of hematology, with an approximate annual test volume of 39,018. 2. Three out of three test reports reviewed during the survey (#5516813, 6932121 and 5380116) failed to include the correct laboratory address where the testing was performed. 3. At the time of the survey conducted on April 23, 2025, the laboratory address listed in the CLIA database for CLIA# 03D0680709 was 3621 N Wells Fargo Ave, Scottsdale, AZ 85251. 4. The test reports indicated above listed the resulting lab as "Honorhealth Cancer Care, 3501 N Scottsdale Rd Ste 300, Scottsdale, AZ 85251." 5. The TC-1 interviewed on 4/23/25 at 10:21 AM confirmed that the laboratory address listed on the test reports referenced above was not correct.</p>