

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 03D1026968	(X3) Date Survey Completed 11/29/2018
Name of Provider or Supplier Fry Laboratories Llc	Street Address, City, State 14807 N 73rd St Ste 102, Scottsdale, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6127	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least semiannually during the first year the individual tests patient specimens.</p> <p>This STANDARD is not met as evidenced by: Based on lack of documentation for a semi-annual competency evaluation for one testing personnel and interview with the facility personnel, the technical supervisor failed to evaluate and document the performance of individuals responsible for high complexity testing during the first year the individual tested patient specimens. Findings include: 1. No semi-annual competency evaluation documentation was presented for review for one testing personnel who began patient testing in October 2016. 2. The facility personnel confirmed that the laboratory failed to have documentation of a semi-annual competency evaluation for the testing personnel indicated above.</p>