

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 03D2006536	(X3) Date Survey Completed 06/05/2019
Name of Provider or Supplier Pdp Az Dermatopathology Lab	Street Address, City, State 6320 W Union Hills Dr, Bldg A Ste 200, Glendale, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6128	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least annually after the first year, unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individual's performance must be reevaluated to include the use of the new test methodology or instrumentation.</p> <p>This STANDARD is not met as evidenced by: Based on lack of testing personnel competency evaluation documentation and interview with the facility personnel, it was determined that the technical supervisor did not evaluate and document the performance of two testing personnel at least annually.* Findings include: 1. The laboratory performs testing under the sub-specialty of Histopathology, with an approximate annual test volume of 22,000. 2. No documentation of annual competency assessment for 2017 and 2018 was presented for review for two out of two testing personnel who performs the gross description on patient specimens. 3. The facility personnel confirmed that no annual competency evaluation was performed for the testing personnel indicated above during 2017 and 2018. * This is a repeat deficiency from the survey conducted on 12/29/2016.</p>