

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 03D2118144	(X3) Date Survey Completed 05/04/2022
Name of Provider or Supplier Evernorth Care Group	Street Address, City, State 9069 W Thunderbird Rd, Peoria, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6054	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on lack of competency evaluation documentation for review and interview with the facility personnel, the technical consultant failed to evaluate and document the performance of individuals responsible for moderate complexity testing at least annually. Findings include: 1. During the survey conducted on May 4, 2022, the laboratory failed to provide documentation of a completed annual competency evaluation for one testing personnel from 2020, 2021 and 2022. 2. The facility personnel confirmed that the laboratory failed to provide documentation of a completed annual competency evaluation from 2020, 2021 and 2022 for the testing personnel indicated above.</p>