

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  04D0465328	<b>(X3) Date Survey Completed</b>  04/12/2019
<b>Name of Provider or Supplier</b>  Barry V Thompson, Md, Pa	<b>Street Address, City, State</b>  103 East Third Avenue, Crossett, AR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5211</b>	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(a)</p> <p>The laboratory must review and evaluate the results obtained on proficiency testing performed as specified in subpart H of this part.</p> <p>This STANDARD is not met as evidenced by:                      . Through a review of 2018 American Proficiency Institute (API) proficiency testing results, performance review and corrective action form, lack of documentation, as well as interview, it was determined the laboratory failed to review and perform corrective action for one out of six proficiency testing events. As evidenced by: A. A review of the API Hematology proficiency testing results revealed the laboratory scored 20% for the test of Red Blood Cells and 40% for the test of Hematocrit in the second proficiency testing event of 2018. B. A review of the performance and corrective action form for the second Hematology proficiency testing event of 2018 revealed there was no documentation that corrective action for these results had been performed. C. In an interview on 04/12/2019 at 10:30, the general supervisor confirmed there was no documentation of corrective action performed for the second proficiency testing event of 2018.</p>