

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 04D0465341	(X3) Date Survey Completed 10/28/2020
Name of Provider or Supplier Family Clinic Of Ashley County Pa	Street Address, City, State 909 Unity Road, Crossett, AR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6056	<p>CLINICAL CONSULTANT CFR(s): 493.1415</p> <p>The laboratory must have a clinical consultant who meets the qualification requirements of 493.1417 of this part and provides clinical consultation in accordance with 493.1419 of this part.</p> <p>This CONDITION is not met as evidenced by: . Family Clinic of Ashley County Laboratory failed to fill the position of Clinical Consultant as cited at D6059.</p>
D6059	<p>CLINICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1419(a)</p> <p>The clinical consultant must be available to provide clinical consultation to the laboratory's clients.</p> <p>This STANDARD is not met as evidenced by: . Through a review of the CMS 209 Laboratory Personnel Report, lack of documentation, and interviews with staff, it was determined the laboratory failed to designate a clinical consultant to provide opinions to laboratory's clients concerning the diagnosis, treatment and management of patient care as evidenced by. A. A review of the CMS 209 revealed the listing of laboratory's personnel positions: 1) Laboratory Director; 2) Testing personnel. No listing for Clinical Consultant. B. The surveyor requested the name and credentials of Clinical Consultant for the Laboratory. None was provided. C. In an interview on 10/28/2020 at 1000, the Laboratory Director confirmed the facility had not designated a Clinical Consultant to render opinions concerning the diagnosis, treat and management of the Laboratory's Clients.</p>